




## Porter Standard Forms




## Porter Triangles & Trapezoid Forms




## Porter Keyhole & Teardrop Forms



## Porter Knock-Out Forms



In cases where clearance per side ( $\emptyset$ ) is  $.08 \emptyset$  or less Porter will break the sharp corners to eliminate interference, when punches, and/or guides and dies are ordered together.



**VIEWS:** Shown as in-die position. This is reflected view for punch and guide, plan view (thru cutting end) of die button. See page 39 for details.

**CENTERING:** Forms are centered to the shank or body as shown. Exception being forms Z09 and Z15, will not be centered on P due to clearance.

When Ordering Forms Specify: Qty Mat. Type Code L2/L Form W P R Locate  
 5 M2 ( ) Z 010 1980 Z-06 4.0 6.0 1.0 LM1

